DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-018287 Address: 333 Burma Road **Date Inspected:** 24-Nov-2010

City: Oakland, CA 94607

OSM Arrival Time: 645 **Project Name:** SAS Superstructure **OSM Departure Time:** 1845 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Shi Lei. **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Orthotropic Box Girder (OBG)

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Amit K. Juvekar, was present during the times noted above for observations relative to the work being performed.

Trail assembly yard, 12AW.

Segment 12AW moved to Trial Assembly Yard for further processing. The attached photographs provide additional detail.

Trial assembly yard, 11DW-11EW, SP-E7.

SMAW Critical Repair welding of weld joint OBW11C-009 (CWR # B-CWR2269); located at Trial assembly yard. Welder is identified as 040611; ZPMC Quality Control Inspector (QC) is identified as Shi Lei. The welding variables recorded by Quality Control Inspector (QC) appeared to comply with the Applicable WPS: WPS-345-SMAW 1G (1F)-FCM-Repair-1.

Trial assembly yard, 11DE-11EE, EP-B3.

SMAW Critical Repair welding of weld joint OBE11A-010 (WRR # B-WR17689); located at Trial assembly yard. Welder is identified as 044515; ZPMC Quality Control Inspector (QC) is identified as Wang Li Yang. The welding variables recorded by Quality Control Inspector (QC) appeared to comply with the Applicable WPS: WPS-345-SMAW 1G (1F) FCM-Repair-1.

This QA Inspector carried out NDE on following Trail assembly yard, 11CE-11DE.



WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA Inspector performed verification Ultrasonic Testing (ABF Request No: 11232010-1) in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a separate data sheet that Caltrans QA generates after performing a joint inspection with ABF ultrasonic testing personnel. The location of the inspection was identified as weld between Edge panels at the transverse splice between OBG segment 11CE-11DE. The weld designations were as;

OBE11A-001. (11CE-11DE, EP-F9);

Trail assembly yard, 11CE-11DE.

This QA Inspector performed verification Ultrasonic Testing (ABF Request No: 11232010-1) in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a separate data sheet that Caltrans QA generates after performing a joint inspection with ABF ultrasonic testing personnel. The location of the inspection was identified as weld between Deck panels at the transverse splice between OBG segment 11CE-11DE. The weld designations were as;

OBE11A-003, 004. (11CE-11DE, DP-A1, A2);

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 1500.042.2372, who represents the Office of Structural Materials for your project.

Inspected By: Juvekar, Amit Quality Assurance Inspector

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Reviewed By: Dsouza, Christopher QA Reviewer